

SPARE PARTS LIST

FOR 2-TON "SPEED" WINCH (WIRE)

Drawing No.	Part No.	Description	Quantity
1	WS2004	Right-hand side plate	1
2	WS2001	Left-hand side plate	1
3	WAA001	Drum (wire)	1
4	WS2003	Drive shaft	1
5	WA2001	Body shaft	5
6	WB2001	Hand arm (left-hand)	1
7	PRH12	Revolving handle	1
8	WBA001	Ratchet gear	1
9	WBA002	Drive shaft collar	1
10	WBA003	Brake pad	2
11	WSHPI ½	Stop washer	1
12	PN112	Lobe knob	1
13	NUTPLH12	M12 Half nut	1
14			
15	WSHP020	M20 Washer	1
16	ROPES0001	8mm Rope	1
17	WBS001	Ratchet spigot	1
18	WBA004	Double ratchet	1
19	NUTNYP12	M12 Nyloc nut (P type)	11
20	WSHP012	M12 Washer	11
21	GRB0810	M8 Grub Screw	
22	SCAP0640	M6 x 40 Socket cap	1
23	NUTNYP06	M6 Nyloc nut (P type)	1
24	NUTPLH12	M12 Half Nut	2
25	WSHS12	M12 Spring washer	2